

HIGHLIGHT ON KERALINE PRODUCTS

How to improve the process and increase productivity (DCR)?



Avoid welding both sides of the metal part NOT NECESSARY TO TURN THE METAL PARTS



Nice appearance of the root pass

CURVED OR FLAT



Save filler metal REDUCES OVERHANG



OUR KERALINE IS NOT SENSITIVE TO AMBIENT TEMPERATURE VARIATIONS

Welding material

Support tape

(to be glued to the welding material)

Ceramic part

(many shapes to choose for the best adjustment)

Keraline support type:

Ceramic on aluminum-tape

Articulated, Flexible following the parts geometry, adjustable, heat resistant, easily detachable after welding.

Ceramic on metallic support

Quick implementation, easily positioned, adjustable, heat resistant.

Welding processes

- SAW
- GMAW
- FCAW
- SMAW

Potential customer

Canister, reservoir, cistern, difficult accessibility and x-bevel manufacturer

Application

- Butt weld square or beveled
- Outside welding for tank
- Circumferential weld (tank, valve, etc.)
- User of "copper" backing, which can be replaced by ceramic

7

BENEFITS

For a well-made welding bead:


- Without copper contamination
- Without risk of burn through in the first pass position (used as a support)
- Without re-welding
- Without risk of lack of fusion
- No turning of the work piece
- Bigger root thickness permits higher welding current for the hot pass
- An increase in first pass deposit rate
- Wide root gap
- Total penetration without turning the parts to be welded
- Total penetration of joints difficult to access in reverse position
- Smooth profile of the root pass

For a well-made weld preparation before welding:

- Ideal to compensate for variations in preparation of sheet edge backlashes
- Easy to use (adhesive/metallic support
- Simplify chamfering preparations

For higher productivity:

- Without gouging operation
- Without grinding operation
- Provides time saving and high quality
- Easy-to-use slats technique




KERALINE has a very low moisture absorption rate and a high melting point, allowing use at high welding intensity, up to 600A.

INSTRUCTIONS FOR USE

- Slat plating on welding parts should be as accurate as possible
- Deformation of parts during welding results in adhesive detachment and lifting of ceramic slat, in some cases
- Requires cleanliness of application surfaces of support ceramic backing adhesives

- Provide accessibility to remove the ceramic backing
- Use the dotted red line marked, on the KERALINE, to allow centering and correctly position the ceramic backing.
- Positioning of the support slat is critical to the appearance of the penetration bead and the weldability of the first pass.


Incorrect:




ATTENTION: Do not select a too small radius of the circular or flat ceramics when butt welding.

Tube Diameter Lower <400 risk of extra thickness at the junctions of the ceramic backing.


Correct:




Without gap between metal plates




With gap between metal plates




Without gap between metal plates



With gap between metal plates



X-bevel without gap




Cylindrical / round ceramic backing: Diameter to be determined according to the weld preparation and gap

4 HIGHLIGHT ON KERALINE PRODUCTS

OUR LINCOLN ELECTRIC OFFER - KERALINE

Choice of KERALINE slat type depending on the welding process:

	KERALINE TM2	KERALINE TM1	KERALINE TR 6	KERALINE TR 5	KERALINE TR 4	KERALINE TR3	KERALINE TR2	KERALINE TR1	KERALINE TF 3	KERALINE TF 2	KERALINE TF1	KERALINE TA3	KERALINE TA 2	KERALINE TA1
ММА	~	~	~	~	~	~	•	~	~	_	_	~	_	_
TIG	~	~	-	-	-	-	-	-	-	~	~	-	~	~
MIG/MAG	~	~	•	~	~	~	~	•	~	~	~	~	~	~
SAW	~	~	_	-	-	-	_	_	_	_	-	_	-	_



www.lincolnelectric.eu HIGHLIGHT ON KERALINE PRODUCTS

2

Flat with rounded concave groove

Metal core or solid wire without slag

 Application: Medium to heavy thickness



Flat with square concave groove (allows you to clear the slag on the side)

Cored wire with slag, MIG MAG, V-bevel

 Application: Same thickness medium or thick

		Туре	Reference	Dimensions (mm)	3D diagram	Application	Packing	
Ceramic-on-aluminum tape		KERALINE TA1-6 mm	W000010391	<u>27</u> → <u>6</u> <u>8</u> + <u>1</u>				
	2	KERALINE TA2-9 mm	W000010392	0 ± 27 → 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 0 1 0 0 0 0 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			600 mm / piece 10 pieces per bag (6 meters) 6 bags/carton (36 meters)	
		KERALINE TA3-13 mm	W000010393	27 13 0, 1 13 0, 1 13				
		KERALINE TF1-6 mm	W000010394	27 © 1				
	3	KERALINE TF2-9 mm	W000010395	27 E + 9 E + 1 E + 1			600 mm / piece 10 pieces per bag (6 meters) 6 bags/carton (36 meters)	
		KERALINE TF3-13 mm	W000010396	27 13 12 13 14				
	KERALINE TJ10 T FULL PENETRATION		W000262368	17 A = 300		4	600 mm / piece 10 pieces per bag (6 meters) 6 bags/carton (36 meters)	
		SET OF CERAMIC BACKING RAD 150	W000275493				16 pieces /Circle 18 Circles/carton (18 meters)	
		SET OF CERAMIC ACKING RAD 200	W000275532	1.3			4 pieces/Segment 20 Segments / SET 12 Sets/carton (12 meters)	
		SET OF CERAMIC BACKING RAD 100	W000404095				12 pieces /Circle 22 Circles/carton (22 meters)	
Ceramic-on- metallic support	KEI	RALINE TM1-13 mm	W000010403		110		600 mm / piece 10 pieces per bag (6 meters) 7 bags/carton (42 meters)	
	KEF	RALINE TM2-18 mm	W000010404	0.1 18 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 18 0.0 1 1			600 mm / piece 9 pieces per bag (5.4 meters) 5 bags/carton (27 meters)	

APPLICATION EXAMPLE

Tank - Reservoir



Avoids back pass (on the other side), protection of molten metal, flexibility, adapts to a wide range of sizes.



Without Ceramic backing means:

Time for:

- Welding first pass without backing and filling first side
- Flipping the piece over
- Gouging operations down to sound metal
- Crack detection operation
- Control operation
- Filling (re welding)

As well as the cost of the consumable used.

The saving for the customer is variable depending on labour cost and fixed costs of the company.

Allows welding outside the tank



CUSTOMER ASSISTANCE POLICY

The business of The Lincoln Electric Company® is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for information or advice about their use of our products. Our employees respond to enquiries to the best of their ability based on information provided to them by the customers and the knowledge they may have concerning the application. Our employees, however, are not in a position to verify the information provided or to evaluate the engineering requirements for the particular weldment. Accordingly, Lincoln Electric does not warrant or guarantee or assume any liability with respect to such information or advice, Moreover, the provision of such information or advice does not create, expand, or alter any warranty on our products. Any express or implied warranty that might arise from the information or advice, including any implied warranty of merchantability or any warranty of fitness for any customers' particular purpose is specifically disclaimed.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change — This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.eu for any updated information.



